Wethersfield Fire Station Case Study

Details: Removal of existing drying cupboard and installation of standard free standing mobile drying system within newly formed drying area as part of a full station refurbishment.

Comments: "It took 3 to 4 days to dry fire kit in the old drying cupboard and the station was often "off the run" as both sets of our kit were wet".

Wethersfield Fire Station

Before TOP TROCK Drying System

Installation of TOP TROCK Drying System